

TOOL LIST:

Section 2.11 Journeymen will furnish themselves with the following hand tools in good condition:

Knife

Pencil

Hammer

Center punch

Small level

Hacksaw frame

Chalk Line

Pliers (as necessary)

600 volt tester

Small crimping tool

Appropriate measuring tape

Screwdrivers (as necessary)

1/4" tap handle

Crescent wrench (8" or less)

Allen wrenches to 3/8"

Flashlight (no batteries)

Adjustable Square

Keyhole saw handle

Small wire stripper

Chain tong or pipe wrench (14" or less)

Current edition, National Electrical Code

Nut drivers 3/16" to 5/8"

End wrenches 1/4" up to 3/4"

3/8" Socket set 3/8" up to 3/4"

The Employer will provide a safe storage facility for Employees' tools. This is not intended to require separate storage where storage for Employer tools and equipment is provided.

In the event of break-in where proper authorities (police or security personnel) are notified and afforded an opportunity to investigate, the Employer will be required to replace stolen or missing tools.

The Foreman and a Union representative will determine whether or not the employees had a full set of tools in the safe storage facility at the time of the break-in.

The Employer shall furnish all other necessary tools or equipment. The employee shall be responsible for replacement of all tools and equipment furnished him by the Employer which are lost or stolen through negligence on his own behalf, providing the Employer furnishes the necessary lockers, tool boxes, or other safe places of storage.